

BLUTM

P R O D U C T S



BLU Diva X Service manual



ATTENTION

Boards, which contain Electrostatic Sensitive Device (ESD), are indicated. Following information is ESD handling:

- Service personnel should ground themselves by using a wrist strap when exchanging system boards.
- When repairs are made to a system board, they should spread the floor with anti-static mat which is also grounded.
- Use a suitable, grounded soldering iron.
- Keep sensitive parts in these protective packages until they are used.
- When returning system boards or parts like EEPROM to the factory, use the protective packages as described.

Content

1. Product Specification.....	3
2. Exploded View.....	4
3. Tools.....	5
4. Assemble & Disassemble	
Disassembly.....	7
Assembly.....	8
5. Picture of main board	
A&B side of PCBA	10
A&B of PCBA Layout.....	11
6. System Block Chart.....	12
7. Unit Circuit Map	13~20
8. Trouble Shooting Guide	21~39
9. Upgrading & IMEI writing.....	40~48
10. CIT testing.....	49

Chapter 1 Product Specification




Diva X Features & Functions

- Dual SIM Dual Standby Single Connection
- Fashion bar phone
- BT 3.0
- FM Radio
- Multi-Media application
- T-Flash (Support 8G SD-Card)
- QVGA240*320
- 0.3 Mega-H /1.3 Mega-S
- MP3, Midi, Amr, Wav
- USB2.0 Mini USB

Specifications:

GSM Band: 900MHz/1800MHz
 Display: QVGA240*320
 Camera: 0.3 Mega-H /1.3 Mega-S
 Talk time: 700 min
 Stand-by: 270 hour
 Lithium Battery: 1400MAH Li-ion Battery
 USB Data cable: USB 2.0

Chapter 2 Exploded View



Chapter 3 Tools



Solder iron



Hot Air Gun




Power Supply




Multimeter



Solder wire, Flux






PC, Download cable





Others

Chapter 4 Disassembly & Assembly

4.1 Disassemble






Finished.

Chapter 5 Picture of PCBA

5.1 Side A


PCBA (Side A) Location of components




5.2 Side B

PCBA (Side B) Location of Components


Side B




5.3 PCBA Layout side A



5.4 PCB Layout Side B



Chapter 6 System Block Chart



Chapter 7 Unit Circuit

7.1.1 System Overview

MT6250 is a GSM/GPRS handset chip solution which integrates RF, analog baseband, digital baseband as well as Power Management Unit(PMU) and can greatly reduce the component count and make a smaller PCB size MT6250 including Bluetooth and FM. Besides, MT6250 is capable of Single Antenna Interference Cancellation (SAIC) and AMR speech Based on a 32-bit ARM7EJ-S RISC

Processor, MT6250 provides an unprecedented platform with high quality modem performance. The typical application diagram is shown as Figure 1.






Figure 2 Top view of MT6252 11.6 x 12.1 mm 0.5 mm pitch TFBGA package


7.1.2 Baseband & CPU





7.1.3 Baseband - Keypad




7.1.4 Clock 32.768KHZ Circuit




7.1.5 CPU to Flash



7.1.6 SIM data output



7.4 I/O Interface (5 PIN)



7.5.1 System


The SKY7756X is a dual-band transmit and receive front-end module(FEM) with integrated power Amplifier control (iPAC) for cellular handsets comprising GSM900 and DCS1800 operation. The FEM has capability in applications of U S and euro dual-band platforms. Designed in a low profile, compact form factor, the SKY77569 offers a complete Transmit VCO-to-Antenna and Antenna-to-receive SAW filter solution. The FEM also supports Class 12 General Packet Radio Service (GPRS) multi-slot operation.



7.5.2 power amplifier





7.6 SIM circuit




Chapter 8 Trouble shooting guide

Can't Download




Cannot power on-current swing instability


Cannot power on-low or no current




Cannot Power on-large current




Repair flow for phone dead




No display or display abnormality




Test process for Key can't work





Key light can't work


Insert SIM Repair Process





N0/weak signal trouble shooting





No/Low sound from Speaker


Receiver low voice or no voice

No/Low sound from MIC


Does not charge - remind error charge

Does not charge - no charge


Does not charge - does not recognize charging

Stand-by short time

Can't read T-Flash card



Can't successfully take picture



Chapter 9 Firmware Upgrading Guide

9.1 Firmware Upgrading

9.1.1 Install USB driver


The maximum downloading speed can be up to 921600bit/s when using USB-Serial cable.

The driver need to be installed before using the USB cable.



Please keep the USB cable unplugged when installing the driver.


Plug the USB cable when installing is completed. And check device manager of the PC.




9.1.2 Run the “Flash_tool.exe” of FlashTool_v5.1112.00



9.1.3 Please select “Options”-“COM port”-Choose the port which is same as the one in “Device Manager”.




9.1.4 Select “Options”-“Format FAT (DISABLED)...” and please do NOT select “validation”.




9.1.5 Please select “Format FAT”.




9.1.6 Select "Options"- "Backup and Restore", then select the "Backup -> Download/format -> Restore".




9.1.7 Click the "Download Agent" and select the file "MTK-ALLInOne-DA.bin".




9.1.8 Click the “Scatter/config file” and select the “scat36_11A_GEMINI.txt”.




9.1.9 Power off the handset, remove the battery, click “Download”, and connect the cable with handset, then insert the battery, press the power on button, the gray, red, blue, green and gray progress bar shall appear. Then upgrade would be completed when appear “OK”.




9.1.10 Backup the data. (gray progress bar)




9.1.11 Connect to phone. (red progress bar)



9.1.12 Downloading is in process. (blue progress bar)



9.1.13 Downloading is completed.



9.1.14 Power on phone and input “*#84666*#”, select “one key Restore”, phone will be reboot, then the user’s setting could be eliminated entirely.

Description: can't power on(also upgrade software fail)

Root cause: red scroll 100% run completely when upgrade software, the detail as figure 1, also it prove power supply, clock is normal and defective typical issue is focus on CPU or FLASH poor soldering or damage, and maybe software do not fit for hardware.

Corrective action: check software fit for hardware whether or not, resoldering CPU and FLASH or exchange new CPU and FLASH.





图 1 (figure 1)

Description: E930 can't power on (handset is dead when upgrade software.) details as figure 2.

Root cause: the power supply and clock both work on as common during upgrade software.

The typical defective issue as poor soldering or go to fall, other way as exchange CPU or Flash.

Corrective action: re-solder CPU and Flash, or replace them.



Chapter 10 CIT Testing

Input “*#84666*#” in the standby mode.

1. Version: Confirm the firmware version.
2. Echo Loop: Receiver shall produce sound when blowing over the mic.
3. Keypad: Press every button on the handset until the screen is clear.
4. Vibrator : Press “start” then the vibration shall start.
5. Loud SPK: Press “start” the speaker shall work.
6. Ringtone: Press “start” the ringtone shall be played.
7. LED : Press “OK” to test the LED.
8. LCD: Select “Auto Display” LCD shall perform the self-testing.
9. Receiver : Press “start” the receiver shall produce sound.
10. Camera: Menu- Camera, test the capture and shooting, no need to save.